



HMEC Type no.	Corresponding Type no.	ΦD	Φd	Axle	Housing	f1	f2	$L \pm 0.25$
P2540L10	MB2540DU	28	25	$25 \begin{smallmatrix} -0.020 \\ -0.041 \end{smallmatrix}$	$28 \begin{smallmatrix} +0.021 \\ 0 \end{smallmatrix}$			40
P2820L10	MB2820DU	32	28	$28 \begin{smallmatrix} -0.020 \\ -0.041 \end{smallmatrix}$	$32 \begin{smallmatrix} +0.025 \\ 0 \end{smallmatrix}$	1.2	0.6	20
P2825L10	MB2825DU	32	28	$28 \begin{smallmatrix} -0.020 \\ -0.041 \end{smallmatrix}$	$32 \begin{smallmatrix} +0.025 \\ 0 \end{smallmatrix}$			25
P2830L10	MB2830DU	32	28	$28 \begin{smallmatrix} -0.020 \\ -0.041 \end{smallmatrix}$	$32 \begin{smallmatrix} +0.025 \\ 0 \end{smallmatrix}$			30
P2840L10	MB2840DU	32	28	$28 \begin{smallmatrix} -0.020 \\ -0.041 \end{smallmatrix}$	$32 \begin{smallmatrix} +0.025 \\ 0 \end{smallmatrix}$			40
P3020L10	MB3020DU	34	30	$30 \begin{smallmatrix} -0.020 \\ -0.041 \end{smallmatrix}$	$34 \begin{smallmatrix} +0.025 \\ 0 \end{smallmatrix}$			20
P3025L10	MB3025DU	34	30	$30 \begin{smallmatrix} -0.020 \\ -0.041 \end{smallmatrix}$	$34 \begin{smallmatrix} +0.025 \\ 0 \end{smallmatrix}$			25
P3030L10	MB3030DU	34	30	$30 \begin{smallmatrix} -0.020 \\ -0.041 \end{smallmatrix}$	$34 \begin{smallmatrix} +0.025 \\ 0 \end{smallmatrix}$			30
P3040L10	MB3040DU	34	30	$30 \begin{smallmatrix} -0.020 \\ -0.041 \end{smallmatrix}$	$34 \begin{smallmatrix} +0.025 \\ 0 \end{smallmatrix}$			40
P3220L10	MB3220DU	36	32	$32 \begin{smallmatrix} -0.025 \\ -0.050 \end{smallmatrix}$	$36 \begin{smallmatrix} +0.025 \\ 0 \end{smallmatrix}$			20
P3225L10	MB3225DU	36	32	$32 \begin{smallmatrix} -0.025 \\ -0.050 \end{smallmatrix}$	$36 \begin{smallmatrix} +0.025 \\ 0 \end{smallmatrix}$			25
P3230L10	MB3230DU	36	32	$32 \begin{smallmatrix} -0.025 \\ -0.050 \end{smallmatrix}$	$36 \begin{smallmatrix} +0.025 \\ 0 \end{smallmatrix}$			30
P3240L10	MB3240DU	36	32	$32 \begin{smallmatrix} -0.025 \\ -0.050 \end{smallmatrix}$	$36 \begin{smallmatrix} +0.025 \\ 0 \end{smallmatrix}$			40
P3520L10	MB3520DU	39	35	$35 \begin{smallmatrix} -0.025 \\ -0.050 \end{smallmatrix}$	$39 \begin{smallmatrix} +0.025 \\ 0 \end{smallmatrix}$			20
P3525L10	MB3525DU	39	35	$35 \begin{smallmatrix} -0.025 \\ -0.050 \end{smallmatrix}$	$39 \begin{smallmatrix} +0.025 \\ 0 \end{smallmatrix}$			25
P3530L10	MB3530DU	39	35	$35 \begin{smallmatrix} -0.025 \\ -0.050 \end{smallmatrix}$	$39 \begin{smallmatrix} +0.025 \\ 0 \end{smallmatrix}$			30
P3540L10	MB3540DU	39	35	$35 \begin{smallmatrix} -0.025 \\ -0.050 \end{smallmatrix}$	$39 \begin{smallmatrix} +0.025 \\ 0 \end{smallmatrix}$			40
P3820L10	MB3820DU	42	38	$38 \begin{smallmatrix} -0.025 \\ -0.050 \end{smallmatrix}$	$42 \begin{smallmatrix} +0.025 \\ 0 \end{smallmatrix}$			20
P3825L10	MB3825DU	42	38	$38 \begin{smallmatrix} -0.025 \\ -0.050 \end{smallmatrix}$	$42 \begin{smallmatrix} +0.025 \\ 0 \end{smallmatrix}$			25
P3830L10	MB3830DU	42	38	$38 \begin{smallmatrix} -0.025 \\ -0.050 \end{smallmatrix}$	$42 \begin{smallmatrix} +0.025 \\ 0 \end{smallmatrix}$			30